



# The Importance of Geotechnical Engineering Design of Excavated Ponds and Embankments

Proactive By Design.  
Our Company Commitment

John M. Siwula, PE, D GE  
GZA GeoEnvironmental, Inc.





## GOALS OF PRESENTATION

### 1. Define and Illustrate

General Geotechnical Issues Affecting Earthen  
Surface Tailings Impoundments/Embankments



## GOALS OF PRESENTATION

### 2. Illustrate

General Types and Methods of Tailings Impoundment  
Structure Construction and Remedial Measures to Address  
Instability and Seepage



## Why are Tailings Impoundments Of Concern ?

MSHA Investigations From 1990 through 2010  
 Failure Of 5 Tailings Structures Cited as a Primary Reason to  
 Develop New Regulations

1990	Puerto Rico	Limestone Mine	100' High
1992	Wisconsin	Andesite Quarry	70' High
1997	Arizona	Copper Mine	Unspecified Height
2002	Georgia	Sand & Gravel Mine	30' High
2007	California	Sand & Gravel Mine	Unspecified Height





## Consequences

- Release 200 M gals. water and tailings
- Moderate to Extensive Damages to Operations, Plant, Equipment, Property, Environment
- Several Injuries
- No Loss Of Life most occurred off – hours





## Primary Factors Affecting Five Mining Failures

1. Lack of Design By a Knowledgeable Engineer, and/or
2. Lack of Understanding of Geotechnical and Dam Engineering Principles



# Failure Of Coal Ash Dredge Spoil Cell December, 2008 Harriman, Tennessee





# Harriman, Tennessee - Release of 200,000 Cubic Yards of Stored Coal Ash





# 1 Billion Gallons of Flow, Much into Emory River





# Alton, New Hampshire 1996 Privately Owned Impoundment Failure






# General Types of Impoundments






## INCISED SURFACE IMPOUNDMENT



# PARTIALLY INCISED SURFACE IMPOUNDMENT





## Dam Size Classification Corps of Engineers

Often Varies by State:  
But size does not matter per MSHA and Corps

<u>Category</u>	<u>Storage (acre-feet)</u>	<u>Height (feet)</u>
Small	$\geq 15$ and $< 50$	$\geq 6$ and $< 15$
Intermediate	$\geq 50$ and $< 1,000$	$\geq 15$ and $< 40$
Large	$\geq 1,000$	$\geq 40$





## Typical Dam Hazard Classification (Varies By State)

<u>Hazard Classification</u>	<u>Hazard Potential</u>
High	<b>Probable loss of life</b> Major economic losses
Significant	<b>Possible loss of life</b> Major economic losses
Low	Loss of life not expected Minimal property damage



## General Methods Of Construction Tailings Impoundments

Ref. Klohn, E. "Taconite Tailings Disposal Practices", Geotechnical Practices in Mine Waste Disposal, A.S.C.E., New York, NY, 1979, pp 202 – 241.




Depending on the mining operation tailings can consist of a wide range of particle sizes ranging from

- Sand - 0.075 mm to 4.75 mm
- Silt – 0.002 mm to 0.075 mm
- Clay - <0.002 mm

Source AASHHTO




## UPSTREAM CONSTRUCTION METHOD



Use of Tailings is practical but it creates stability and seepage concerns


## UPSTREAM CONSTRUCTION METHOD



### Geotechnical Issues


- Low Shear Strength Tailings – Soft, Loose
- No Internal Drainage – High Water Pressures
- Poor Compaction of Fill Materials
- Steep Side Slopes
- Weak Foundation
- Liquefiable Soils Under Seismic Loads

# CENTERLINE CONSTRUCTION METHOD





# DOWNSTREAM CONSTRUCTION METHOD






## Classical Rotational Dam Failure

DeKalb County, Georgia

Multi-Jurisdictional Hazard Mitigation Plan, February 2011




## Classical Rotational Failure With Liquefaction

Merriespruit Tailings Dam Failure 1994, Virginia, South Africa







# IMPROVEMENT OF SLOPE INSTABILITY



# IMPROVEMENT OF SEEPAGE CONTROL



# DECANT PIPE FAILURE MECHANISMS (TYPICAL)







## Main Points

- Most Failures of Earth Impoundment Structures Due to Misunderstanding of Geotechnical Issues
- Involve a Knowledgeable Geotechnical Engineer in Design, Construction, Operation and Maintenance of Impoundment Structures
- Address MSHA Regulations
- Increased focus by MSHA due to two recent deaths that MSHA attributed to embankment failure



## John M. Siwula, PE, D GE

Associate Principal/Geotechnical Engineer

GZA GeoEnvironmental, Inc.

20900 Swenson Drive, Suite 150

Waukesha, WI 53186

262-754-2576

414-412-9286

[John.siwula@gza.com](mailto:John.siwula@gza.com)

Proactive By Design.  
Our Company Commitment

